

How To Customize Woodwright® Varnish & Stain In Various Climates



CONVERSION VARNISH

Product #9926, 9931, 9934, 9948, 9999, 9988, 9930, 9982

| Per Gallon Additions | 40—59° F | 60—69° F | 70—79° F | 80—89° F | 80—89° F High Humidity | 90° F + |
|----------------------|----------|----------|----------|----------|------------------------|---------|
| TH7100 FLOSOL | 4—6 OZ | 2—4 OZ | X | 2 OZ | 4—6 OZ | X |
| TH3700 SLOW REDUCER | X | X | X | X | X | 2 OZ |

PRECATALYZED VARNISH

Product #8828, 8820, 8814 (lacquer)

| Per Gallon Additions | 40—59° F | 60—69° F | 70—79° F | 80—89° F | 80—89° F High Humidity | 90° F + |
|----------------------|----------|----------|----------|----------|------------------------|---------|
| TH3500 FAST REDUCER | 4—6 OZ | 2—4 OZ | X | X | X | X |
| TH3700 SLOW REDUCER | X | X | X | 2 OZ | 4—6 OZ | 6—8 OZ |

WOODWRIGHT STAINS

Easy Wipe Stain Base and #7 Stain Base

| Per Gallon Additions | 40—59° F | 60—69° F | 70—79° F | 80—89° F | 80—89° F High Humidity | 90° F + |
|-----------------------|----------|----------|----------|----------|------------------------|---------|
| TH3600 MEDIUM REDUCER | 2—4 OZ | X | X | X | X | X |
| TH3700 SLOW REDUCER | X | X | X | X | 4—6 OZ | 6—8 OZ |

35260 CATALYST AMOUNTS FOR VARNISH OVER DARK OILY STAIN (PER GALLON):

Add 5 oz total per gallon 35260 to Woodwright Conversion Varnish #9926, 9934, 9948, 9999, 9988, 9930

Add no more than 4.5 oz total per gallon 35260 to Woodwright Catalyzed Sealer #9931 and 9982